

ABSTRACT:

An ashing method comprises the steps of: holding a substrate having a resist mask formed through an insulating film in a chamber of an ashing apparatus; and applying an RF electric power to activate
5 an oxygen-containing gas introduced in the chamber in order to perform ashing of the resist mask, while an RF electric power is applied to the substrate.